



Can you find the Sea Cloud?





Mast Step rotted wood





Finished Mast Step






Aft Cabin area gutted




More Rot






Old Engine





Engine compartment ready for new engine



New Engine ready to go in





Almost in





Before and after opening up



more rot





Cleaned up and prepped for install of new wood



Fitting in the new wood baking plate



first layer set and drying